

Date: Wednesday, 12/20/2006 11:59:16 AM  
 User: Kim Johnston

## Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: BUSHING
Job Number	: 29996		
Estimate Number	: 10725		
P.O. Number	: <i>N/A</i>	Part Number	: D2652
This Issue	: 12/20/2006 S.O. No. : <i>N/A</i>	Drawing Number	: D2652 REV A
Prsht Rev.	: NC	Project Number	: N/A
First Issue	: <i>N/A</i> Type : MACHINED PARTS	Drawing Revision	: A
Previous Run	: 29332	Material	: <i>N/A</i>
Written By	: <i>[Signature]</i>	Due Date	: 1/15/2007
Checked & Approved By	: <i>[Signature] 06/12/20</i>	Qty:	300 Um: Each
Comment	: Est Rev:B 02.06.13 Now machined in house. NG		

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	M303R0500	303 Round Bar 0.500"
-----	-----------	----------------------



Comment: Qty.: 0.0578 f(s)/Unit Total : 17.3250 f(s)  
 Material: 303 ss .500" Round Bar  
 (M303R0500)  
 Batch: *1108447*

*JF 06/12/20*

2.0	HARDINGE	HARDINGE CNC LATHE SMALL
-----	----------	--------------------------



Comment: HARDINGE CNC LATHE SMALL

1-Turn as per Folio FA250 & Dwg D2652

2-Deburr

*JF 06/12/20*

3.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

*JF 06/12/20* (306)

4.0	QC8	SECOND CHECK
-----	-----	--------------



Comment: SECOND CHECK

*J.L 07/10/05*

5.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: *954*

*[Signature] 07/01/08 (306) R 7/01/08*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes ☒ No ☐ DQA: ED Date: 27/01/08  
 QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 12/20/2006 11:59:17 AM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BUSHING

Job Number: 29996

Part Number: D2652

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



306

Comment: FINAL INSPECTION/W/O RELEASE

08/01/08

Job Completion



08-01-08

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries





DESIGN <i>[Signature]</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE USA, INC. FAIRCHILD INTERNATIONAL AIRPORT, WA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2652	REV. A SHEET 1 OF 1
DATE 97:03:25		TITLE BUSHING	SCALE 1:1

RELEASED  
97/04/25 DS



SHOP COPY  
RETURN TO  
ENGINEERING  
UNCONTROLLED COPY  
SUBJECT TO AMENDMENT  
WITHOUT NOTICE  
WORK ORDER  
NO. 29996

MATERIAL: AISI 303 SS  
NOTE: BREAK ALL SHARP CORNERS 0.010 MAX  
TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED